

Final Reclamation and Stormwater Inspection

March 17, 2025

Operator: COLTON LIMITED LIABILITY CO - 18795

Location ID: 320476

Well Name: LINNEBUR #42-1

Inspection Document #: 718600412

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: LINNEBUR #42-1
Location ID: 320476



Photo 1. Looking south across well location. No oil and gas equipment remains. Access road appears to be in use for oil and gas access.



Photo 2. Looking across the wellbore area. Cropland appears to have been seeded, germination was visible at time of inspection.



Inspection Photos
Location Name: LINNEBUR #42-1
Location ID: 320476



Photo 3. Picture taken looking at location east of the access access road. This portion appears to have been seeded.



Photo 4. Looking west from wellbore.



Inspection Photos
Location Name: LINNEBUR #42-1
Location ID: 320476



Photo 5. Looking west across former tank battery. All equipment has been removed. Tank battery is fenced out from field. Undesirable weeds (Kochia, Russian thistle) are present on tank battery.



Photo 6. Google earth imagery 6/24, former tank battery location (red circle). This area should be returned to crop/pasture.