

Interim Reclamation and Stormwater Inspection

March 17, 2025

Operator: WESTERN OPERATING COMPANY

Location ID: 474009

Well Name: LINNEBUR TANK BATTERY/

Inspection Document #: 718600414

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: LINNEBUR TANK BATTERY/
Location ID: 474009



Photo 1. Looking across tank battery.



Photo 2. Valve is leaking. Stained soil is present beneath valve.

Inspection Photos
Location Name: LINNEBUR TANK BATTERY/
Location ID: 474009



Photo 3. Separator shed on east side of location.




Photo 4. Inside shed. Leaking fittings, valves (green circles). Stained soil and oil rags/trash (red circle). 5 gallon bucket full of oil (blue circle).



Inspection Photos
Location Name: LINNEBUR TANK BATTERY/
Location ID: 474009




Photo 5. Oil in bucket



Photo 6. Unused equipment being stored in separator shed.

Inspection Photos
Location Name: LINNEBUR TANK BATTERY/
Location ID: 474009



Photo 7. Eastern side of separator shed berm. Has been driven over and damaged.



Photo 8. Air inlet of active separator. Multiple bird nests as well as trash, bolts and fittings.

Inspection Photos
Location Name: LINNEBUR TANK BATTERY/
Location ID: 474009



Photo 9. Looking west down south side of location.



Photo 10. looking east overview of location. Location is free of weeds.