

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403979508

Receive Date:

---

Report taken by:

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECMC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27.

This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: <u>PDC ENERGY INC</u>	Operator No: <u>69175</u>	Phone Numbers Phone: <u>(303) 860-5800</u> Mobile: <u>( )</u>
Address: <u>1099 18TH STREET SUITE 1500</u>		
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80202</u>
Contact Person: <u>Karen Olson</u>	Email: <u>karen.olson@chevron.com</u>	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 32449 Initial Form 27 Document #: 403581014

PURPOSE INFORMATION

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: \_\_\_\_\_

SITE INFORMATION

No  Multiple Facilities

Facility Type: <u>WELL</u>	Facility ID: _____	API #: <u>123-21330</u>	County Name: <u>WELD</u>
Facility Name: <u>MDM 33-14</u>	Latitude: <u>40.137160</u>	Longitude: <u>-104.968523</u>	
	** correct Lat/Long if needed: Latitude: <u>40.137138</u>	Longitude: <u>-104.968517</u>	
QtrQtr: <u>NWSE</u>	Sec: <u>14</u>	Twps: <u>2N</u>	Range: <u>68W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>

SITE CONDITIONS

General soil type - USCS Classifications SM Most Sensitive Adjacent Land Use Agricultural

Is domestic water well within 1/4 mile? Yes Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? Yes

**Other Potential Receptors within 1/4 mile**

Nearest Well: Monitoring / Sampling - 1,221' N; Surface Water: Unnamed Creek - 230' ENE; Occupied Building: 916' NW; Livestock: 881' S; FWS Wetlands: 234' E Freshwater Emergent Wetland (PEM1A); Wellhead & Flowline Within 100-Year Floodplain.

Flowline Conflict: Wellhead & Flowline Within 100-Year Floodplain.

**SITE INVESTIGATION PLAN**

**TYPE OF WASTE:**

- E&P Waste       Other E&P Waste       Non-E&P Waste
- Produced Water       Workover Fluids
- Oil       Tank Bottoms
- Condensate       Pigging Waste
- Drilling Fluids       Rig Wash
- Drill Cuttings       Spent Filters
- Pit Bottoms
- Other (as described by EPA)

**DESCRIPTION OF IMPACT**

Impacted?	Impacted Media	Extent of Impact	How Determined
No	GROUNDWATER	Refer to Tables and Figures	Lab Analysis and Field Screening
Yes	SOILS	Refer to Tables and Figures	Lab Analysis and Field Screening

**INITIAL ACTION SUMMARY**

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Pursuant to ECMC Rule 911 a site investigation was conducted on 09/23/2024 pertaining to the MDM 33-14 wellhead cut and cap by Entrada Consulting Group. The wellhead was cut and capped per ECMC rules.

Pursuant to ECMC Rule 911 a site investigation was conducted on 10/17/2024 pertaining to the MDM 33-14 flowline removal by Tasman, INC. Approximately 1,115 feet of flowline was removed. Soil samples were taken along the flowline at any points of material change and/or hammer unions, directional changes, as well as at the bell holes on either side of a waterway, as applicable. The Flowline Pre-Abandonment Notice Document number is 404083777.

**PROPOSED SAMPLING PLAN**

**Proposed Soil Sampling**

Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

Soil samples were collected from the surface in cardinal directions of the wellhead, as defined in the Rule 911.a.(4) guidance document (9/20/21), for field screening purposes. Grab confirmation soil samples were collected at the wellhead and flowline decommissioning. Soil samples taken along flow line were taken at any directional/ material change, hammer unions and every 250 ft. Discrete soil samples were collected for laboratory analysis either in any area of observed hydrocarbon impacts or adjacent to the cut and capped wellhead from native material and below the flowline riser. Soil samples were submitted for laboratory analysis of the full Table 915-1 analytical suite. All samples collected were analyzed by a certified laboratory using approved ECMC laboratory analysis methods.

**Proposed Groundwater Sampling**

Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

During flowline decommissioning groundwater was encountered at two locations (GW01@5' & GW02@4') and grab groundwater samples were collected and analyzed for all organic and inorganic compounds per ECMC Table 915-1; this sample analysis includes, but is not limited to BTEX, naphthalene, 1,2,4- trimethylbenzene (TMB), and 1,3,5-TMB by EPA Method 8260, chloride and sulfate anions by EPA Method 300.0, and total dissolved solids (TDS) by Method SM 2540C.

If groundwater is encountered during the site investigation, grab groundwater samples will be collected and analyzed for all organic and inorganic compounds per ECMC Table 915-1.

**Proposed Surface Water Sampling**

Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

**Additional Investigative Actions**

Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

Assessments were conducted during the removal of the off-location flowline (estimated to be 1,115 feet in length) approximately every 250 feet. Laboratory soil samples were collected below the flowline risers, at the halfway point, and at the changes in direction (N-NW), (NW-NE), and (NE-NW). Visual inspection of the wellhead and flowline areas occurred during abandonment activities. Field personnel field screened all disturbed areas using visual and olfactory senses to determine if laboratory confirmation sampling was required. A detailed summary of wellhead decommissioning activities, including field notes, site photos, figures, and laboratory analytical results, is attached to this Form 27. A detailed summary of flowline decommissioning activities, including field notes, site photos, figures, and analytical results will be attached to a subsequent Form 27.

# SITE INVESTIGATION REPORT

## SAMPLE SUMMARY

### Soil

Number of soil samples collected 2

Number of soil samples exceeding 915-1 2

Was the areal and vertical extent of soil contamination delineated? No

Approximate areal extent (square feet) 200

### NA / ND

ND Highest concentration of TPH (mg/kg) \_\_\_\_\_

-- Highest concentration of SAR 2.11

BTEX > 915-1 No

Vertical Extent > 915-1 (in feet) 6

### Groundwater

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? Yes

Depth to groundwater (below ground surface, in feet) \_\_\_\_\_

Number of groundwater monitoring wells installed \_\_\_\_\_

Number of groundwater samples exceeding 915-1 \_\_\_\_\_

ND Highest concentration of Benzene (µg/l) \_\_\_\_\_

ND Highest concentration of Toluene (µg/l) \_\_\_\_\_

ND Highest concentration of Ethylbenzene (µg/l) \_\_\_\_\_

ND Highest concentration of Xylene (µg/l) \_\_\_\_\_

NA Highest concentration of Methane (mg/l) \_\_\_\_\_

### Surface Water

0 Number of surface water samples collected

0 Number of surface water samples exceeding 915-1

If surface water is impacted, other agency notification may be required.

## OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Five background soil samples were collected from one soil boring advanced near the flowline and analyzed for full ECMC Table 915-1 constituents. Background soil samples were collected from depths ranging between 0.5 to 5 feet below ground surface (ft bgs). A secured analytical data report is pending. Upon receipt of a secured report, background analytical findings will be summarized and provided.

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) \_\_\_\_\_

Volume of liquid waste (barrels) \_\_\_\_\_

Is further site investigation required?

MDM 33-14 flowline decommissioning activities were conducted in October 2024. A secured analytical data report is pending. Upon receipt of a secured report, analytical findings will be summarized and provided, and an SSI will be proposed, as applicable, on a subsequent Form 27.

## REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

### SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

No impacted material caused by oil and gas operations was identified at this time.

### REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

MDM 33-14 flowline decommissioning activities were conducted in October 2024. A secured analytical data report is pending. Upon receipt of a secured report, analytical findings will be summarized and provided, and an SSI will be proposed, as applicable, on a subsequent Form 27.

### Soil Remediation Summary

In Situ

Ex Situ

- \_\_\_\_\_ Bioremediation ( or enhanced bioremediation )
- \_\_\_\_\_ Chemical oxidation
- \_\_\_\_\_ Air sparge / Soil vapor extraction
- \_\_\_\_\_ Natural Attenuation
- \_\_\_\_\_ Other \_\_\_\_\_

- \_\_\_\_\_ Excavate and offsite disposal
- \_\_\_\_\_ If Yes: Estimated Volume (Cubic Yards) \_\_\_\_\_
- \_\_\_\_\_ Name of Licensed Disposal Facility or ECMC Facility ID # \_\_\_\_\_
- \_\_\_\_\_ Excavate and onsite remediation
- \_\_\_\_\_ Land Treatment
- \_\_\_\_\_ Bioremediation (or enhanced bioremediation)
- \_\_\_\_\_ Chemical oxidation
- \_\_\_\_\_ Other \_\_\_\_\_

**Groundwater Remediation Summary**

- \_\_\_\_\_ Bioremediation ( or enhanced bioremediation )
- \_\_\_\_\_ Chemical oxidation
- \_\_\_\_\_ Air sparge / Soil vapor extraction
- \_\_\_\_\_ Natural Attenuation
- \_\_\_\_\_ Other \_\_\_\_\_

**GROUNDWATER MONITORING**

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater was encountered and sampled during flowline decommissioning activities. Two groundwater samples (GW01@5' and GW02@4') were collected along the former flowline location and were submitted for laboratory analysis of BTEXN, TMBs, TDS, Cl-, and SO2-4. A secured analytical data report is pending. Upon receipt of a secured report, groundwater analytical findings will be summarized and provided.

# REMEDIATION PROGRESS UPDATE

## PERIODIC REPORTING

### Approved Reporting Schedule:

Quarterly     Semi-Annually     Annually     Other

### Request Alternative Reporting Schedule:

Semi-Annually     Annually     Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

**Report Type:**     Groundwater Monitoring     Land Treatment Progress Report     O&M Report  
 Other 1Q25 -Timeline Update

## Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Operator does not have site-specific financial assurance for this project; however, Operator has inactive well, blanket, and surface bonding including Surety IDs 106077122, 106473808, and 106473820, as well as commercial general liability and/or umbrella/excess insurance meeting the requirements of Rule 705.b. Operator does not anticipate making an insurance claim for this project.

- Further soil investigation/delineation is required

Costs included herein are estimates only and may change over time based on numerous factors. Accordingly, Operator makes no guarantees as to the accuracy of such cost estimates, thus providing an estimate for the next year below.

Operator anticipates the remaining cost for this project to be: \$ 15000

## WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards \_\_\_\_\_

E&P waste (solid) description \_\_\_\_\_

ECMC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-ECMC Disposal Facility: \_\_\_\_\_

Volume of E&P Waste (liquid) in barrels \_\_\_\_\_

E&P waste (liquid) description \_\_\_\_\_

ECMC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-ECMC Disposal Facility: \_\_\_\_\_

## REMEDIATION COMPLETION REPORT

### REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

If YES:

- Compliant with Rule 913.h.(1).
- Compliant with Rule 913.h.(2).
- Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? \_\_\_\_\_

Does the previous reply indicate consideration of background concentrations? \_\_\_\_\_

Does Groundwater meet Table 915-1 standards? \_\_\_\_\_

Is additional groundwater monitoring to be conducted? \_\_\_\_\_

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

## RECLAMATION PLAN

### RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation will be conducted in accordance with ECMC 1000 Series Rules.

Is the described reclamation complete?  Yes

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim  Final

Did the Surface Owner provide the seed mix? \_\_\_\_\_

If YES, does the seed mix comply with local soil conservation district recommendations? \_\_\_\_\_

Did the local soil conservation district provide the seed mix? \_\_\_\_\_

### SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. 09/23/2024

Proposed date of completion of Reclamation. 03/24/2026

## IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

### PRIOR DATES

Date of Surface Owner notification/consultation, if required. 09/16/2023

Actual Spill or Release date, or date of discovery. \_\_\_\_\_

### SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 09/23/2024

Proposed site investigation commencement. 03/24/2025

Proposed completion of site investigation. 09/24/2025

### REMEDIAL ACTION DATES

Proposed start date of Remediation. 09/24/2025

Proposed date of completion of Remediation. 12/24/2025

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

MDM 33-14 flowline decommissioning activities were conducted in October 2024. A secured analytical data report is pending. Upon receipt of a secured report, analytical findings will be summarized and provided, and an SSI will be proposed, as applicable, on a subsequent Form 27.

**OPERATOR COMMENT**

This SF27 represents a 1Q25 TU for the MDM 33-14 wellhead and flowline decommissioning activities conducted in September and October 2024.

The WH sampling was conducted by Entrada consulting in September 2024 and identified pH, arsenic, and barium exceedances in sample locations WH01@6' and FLR01@4'. A secured analytical data report is attached and data is summarized in the attached Entrada data package.

In October 2024, Tasman conducted sampling activities along the flowline. Upon receipt of a secured laboratory report, analytical findings will be summarized and provided. SF27s will continue to be submitted on a quarterly basis.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Andy Sagen

Title: Environmental Consultant

Submit Date: \_\_\_\_\_

Email: Tas-Chevron-1@tasman-geo.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: \_\_\_\_\_

Date: \_\_\_\_\_

Remediation Project Number: 32449

**COA Type**

**Description**

<u>COA Type</u>	<u>Description</u>
0 COA	

**ATTACHMENT LIST**

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

**Att Doc Num**

**Name**

404138240	SITE INVESTIGATION REPORT
404140069	ANALYTICAL RESULTS

Total Attach: 2 Files

**General Comments**

**User Group**

**Comment**

**Comment Date**

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)