

Inspection Photos

March 24th, 2025

Operator: Simcoe LLC - 10749

Location ID: 326108

Inspection Document #: 714001991

La Plata County, CO

Township: SWNW 30 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Eldridge 30-01 1
Location ID: 326108



Photo 1. View of well pad taken from the access point facing center.

Inspection Photos
Location Name: Eldridge 30-01 1
Location ID: 326108



Photo 2. Weedy debris observed on active pad and lining active pad perimeter.



Photo 3. Weey debris observed in the western fill slope area.

Inspection Photos
Location Name: Eldridge 30-01 1
Location ID: 326108



Photo 4. View of trash in the western portion of the location.

3/24/25
45° NE



Photo 5. Produced water label has peeled and no longer legible.

Inspection Photos
Location Name: Eldridge 30-01 1
Location ID: 326108



Photo 6. Rutting (ranging 10-14 inches in depth) observed along length of access road approaching well pad.