

Inspection Photos

March 24th, 2025

Operator: Simcoe LLC - 10749

Location ID: 326109

Inspection Document #: 714001993

La Plata County, CO

Township: NWNW 31 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Eldridge 31-01 1
Location ID: 326109



Photo 1. View of well pad taken from the access point facing center.

3/24/25
177° S





Photo 3. Produced water tank label has peeled and is now illegible.

Inspection Photos
Location Name: Eldridge 31-01 1
Location ID: 326109



Photo 4. Weedy kochia debris observed throughout the active pad.

Inspection Photos
Location Name: Eldridge 31-01 1
Location ID: 326109



Photo 5. Large portion of western interim reclamation remains with bare soils and weedy debris. Additional reclamation efforts are needed in this area.