

Inspection Photos

March 24th, 2025

Operator: BMG Drilling Corporation - 7650

Location ID: 325330

Inspection Document #: 714001997

La Plata County, CO

Township: NWNW 10 33N 910W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Ute 6
Location ID: 325330

3/24/25
199° S



Photo 1. View of the project area taken from the northern edge facing center. Note: location remains unreclaimed.

Inspection Photos
Location Name: Ute 6
Location ID: 325330

3/24/25
169° S



Photo 2. Stormwater BMPs have been installed in the location fill slope.

Inspection Photos
Location Name: Ute 6
Location ID: 325330

3/24/25
20° N



Photo 3. View of access road that remains unreclaimed.