

WELL NAME: KATLYNN 12-25, API #: 071-06864, INSP. # 716300704




PHOTO 1: WELL SIGN







**PHOTO 2: LOCATION.**







**PHOTO 3: WELLHEAD AND EQUIPMENT.**







**PHOTO 4: OILY WASTE NEAR COMPRESSOR. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. CA DATE 3-31-2025.**







**PHOTO 5: AREA OF IMPACTED SOIL NEAR METER HOUSE. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. CA DATE 3-31-2025.**





**PHOTO 6: OILY WASTE IN OPEN CONTAINMENT (COMPRESSOR SKID). DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE OR TREAT IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 3-26-2025.**

