

Inspection Photos  
Location Name: Vicki 21-24  
Location ID: 305538



Photo 1 well head and equipment

Photo 2 production equipment and tank battery

**Inspection Photos**  
**Location Name: Vicki 21-24**  
**Location ID: 305538**



**Photo 3 stained soil inside containment**

**Photo 4 stained soil inside containment**