

Third Party									
Removal Date									
Sample taken?									
PID Readings									
Photo Number(s)									

Other Facility Equipment

Equipment type	Dump Line				
Equipment Condition	UNKNOWN				
Age	Years				
Soil Impacts	None				
PID Readings	0.1				
Sample taken?	DL-SS-01				
Photo Number(s)					

Other observations regarding other facility or third party equipment:

Summary

Was impacted soil identified?		No	Yes - less than 10 cubic yards	Yes - more than 10 cubic yards
Total number of samples field screened:	5	Total number of samples collected:	5	
Highest PID Reading:	756.0	Total number of samples submitted to lab for analysis:	4	
If more than 10 cubic yards of impacted soil were observed:				
Vertical extent:		Estimated spill volume:		
Lateral extent:		Volume of soil removed:		
Is additional investigation required?				
Was groundwater encountered during the investigation?				
No	Yes - not impacted or in contact with impacted soils	Yes - groundwater impacted and/or in contact with impacted soils		
Measured depth to groundwater:		Was remedial groundwater removal conducted?	Yes	No
Date Groundwater was encountered:		Commencement date of removal:		
Seen on groundwater?	Yes	No	Volume of groundwater removed prior to sampling:	
Free product observed?	Yes	No	Volume of groundwater removed post sampling:	
Total number of samples collected:		Total Volume of groundwater removed:		
Total number of samples submitted to lab for analysis:				