

Inspection Photos
Location Name: Stallings 2-12
API Number: 125-08237



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: Stallings 2-12
API Number: 125-08237



3. Lease sign at gathering location.



4. Gas meter inside meter shed.

Inspection Photos
Location Name: Stallings 2-12
API Number: 125-08237



5. Production related debris at gas meter shed.



6. Gathering location overview.