

Inspection Photos
Location Name: Jack Berger A Tank Battery
Location ID: 446479



Photo 1 Location



Photo 2 Horizontal Heated Separator.

Inspection Photos
Location Name: Jack Berger A Tank Battery
Location ID: 446479



Photo 3 Unmarked flow lines



Photo 4 Flow line manifold.

Inspection Photos
Location Name: Jack Berger A Tank Battery
Location ID: 446479



Photo 5 Tank battery sign.



Photo 6 Tank battery.

Inspection Photos
Location Name: Jack Berger A Tank Battery
Location ID: 446479



Photo 7 Tank battery sign.