

Inspection Photos

Location Name: QB Energy SHAEFFER 18-3 (C18E) Pad

Location #: 324026



Photo # 8218 From Entrance to location




Photo # 8219 Location

Inspection Photos
Location Name: QB Energy SHAEFFER 18-3 (C18E) Pad
Location #: 324026



Photo # 8220 Location



Photo # 8221 Location

Inspection Photos

Location Name: QB Energy SHAEFFER 18-3 (C18E) Pad

Location #: 324026




Photo # 8222 Location



Photo # 8223 Wellhead sign laying on ground near separator
/signage not properly posted

Inspection Photos
Location Name: QB Energy SHAEFFER 18-3 (C18E) Pad
Location #: 324026



Photo # 8224 Weeds in secondary containment



Photo # 8225 Weeds in secondary containment

Inspection Photos

Location Name: QB Energy SHAEFFER 18-3 (C18E) Pad

Location #: 324026



Photo # 8226 Weeds in secondary containment

