

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/20SESE

Location ID: 335470

Date: 3/26/2025



Mar 26, 2025 at 11:47:18  
Silt CO 81652  
United States

Location Overview – Photo #07644



Mar 26, 2025 at 11:55:12  
Silt CO 81652  
United States

Location – Photo #07665

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/20SESE

Location ID: 335470

Date: 3/26/2025



Location – Photo #07645



Location – Photo #07648




## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/20SESE

Location ID: 335470

Date: 3/26/2025



Illegible Tank Label – Photo #07655



Illegible Tank Label – Photo #07657



## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/20SESE

Location ID: 335470

Date: 3/26/2025



Illegible Wellhead Sign – Photo #07666



Illegible Wellhead Sign – Photo #07667



## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/20SESE

Location ID: 335470

Date: 3/26/2025



Illegible Wellhead Sign – Photo #07668



Illegible Wellhead Sign – Photo #07669

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/20SESE

Location ID: 335470

Date: 3/26/2025



Illegible Wellhead Sign – Photo #07670



Illegible Wellhead Sign – Photo #07671





## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/20SESE

Location ID: 335470

Date: 3/26/2025



Weeds – Photo #07646



Weeds – Photo #07647



## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/20SESE

Location ID: 335470

Date: 3/26/2025



Weeds – Photo #07672



Weeds – Photo #07673



## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/20SESE

Location ID: 335470

Date: 3/26/2025



Weeds – Photo #07674



Weeds – Photo #07675



## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/20SESE

Location ID: 335470

Date: 3/26/2025



Weeds – Photo #07676



Weeds – Photo #07677



## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/20SESE

Location ID: 335470

Date: 3/26/2025



Weeds – Photo #07658



Weeds – Photo #07659



## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SPECIALTY-66S92W/20SESE

Location ID: 335470

Date: 3/26/2025



Staining – Photo #07661



Leak on Load Line Fitting – Photo #07660