

Inspection Photos
Location Name: Nichols Tank Battery
Location ID: 429183



Photo 1 Location.



Photo 2 Horizontal Heated Separators.

Inspection Photos
Location Name: Nichols Tank Battery
Location ID: 429183



Photo 3 Horizontal Heated Separators.

Photo 4 VRU.

Inspection Photos
Location Name: Nichols Tank Battery
Location ID: 429183



Photo 5 ECD.



Photo 6 LACT house.

Inspection Photos
Location Name: Nichols Tank Battery
Location ID: 429183




Photo 7 Tank battery.

Photo 8 Tank battery signs.

Inspection Photos
Location Name: Nichols Tank Battery
Location ID: 429183



Photo 9 Tank battery.

Photo 10 Pig station.