

Inspection Photos

Location Name: QB Energy FEDERAL 11-15A (RJ11) Pad

Location #: 324423



Photo # 7757 From Entrance to location

Photo # 7758 Location

Inspection Photos
Location Name: QB Energy FEDERAL 11-15A (RJ11) Pad
Location #: 324423



Photo # 7759 Location



Photo # 7760 Location

Inspection Photos
Location Name: QB Energy FEDERAL 11-15A (RJ11) Pad
Location #: 324423



Photo # 7761 Location



Photo # 7762 Location

Inspection Photos
Location Name: QB Energy FEDERAL 11-15A (RJ11) Pad
Location #: 324423



Photo # 7763 Barbed wire fence needs maintenance/wildlife hazard



Photo # 7764 Barbed wire fence needs maintenance/wildlife hazard

Inspection Photos

Location Name: QB Energy FEDERAL 11-15A (RJ11) Pad

Location #: 324423



Photo # 7765 Barbed wire fence needs maintenance/wildlife hazard



Photo # 7766 Barbed wire fence needs maintenance/wildlife hazard

Inspection Photos

Location Name: QB Energy FEDERAL 11-15A (RJ11) Pad

Location #: 324423



Photo # 7767 Barbed wire fence needs maintenance/wildlife hazard



Photo # 7768 Barbed wire fence needs maintenance/wildlife hazard

Inspection Photos

Location Name: QB Energy FEDERAL 11-15A (RJ11) Pad

Location #: 324423



Photo # 7769 Barbed wire fence needs maintenance/wildlife hazard



Photo # 7770 Barbed wire fence needs maintenance/wildlife hazard

Inspection Photos

Location Name: QB Energy FEDERAL 11-15A (RJ11) Pad

Location #: 324423



Photo # 7771 Barbed wire fence needs maintenance/wildlife hazard



Photo # 7772 Barbed wire fence needs maintenance/wildlife hazard

Inspection Photos

Location Name: QB Energy FEDERAL 11-15A (RJ11) Pad

Location #: 324423



Photo # 7773 Barbed wire fence needs maintenance/wildlife hazard