

Final Reclamation and Stormwater Inspection

March 25, 2025

Operator: BAYSWATER EXPLORATION & PRODUCTION LLC - 10261

Location ID: 445729

Well Name: Anderson 4 and 5 Tank Battery Locat/

Inspection Document #: 718600439

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Anderson 4 and 5 Tank Battery
Locat/
Location ID: 445729



Photo 1. Looking southeast across tank battery location. No oil and gas equipment remains.



Photo 2. Looking east down the former tank battery. Large bare spot is present at the tank battery. Vegetation is primarily list C noxious weed Downy Brome. Undesirable weed Kochia is also present on location.



Inspection Photos

Location Name: Anderson 4 and 5 Tank Battery

Locat/

Location ID: 445729



Photo 3. Vegetation and bare spot on tank battery.




Photo 4. Looking west across tank battery. See photo 2 comments.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 718600439

Inspection Photos
Location Name: Anderson 4 and 5 Tank Battery
Locat/
Location ID: 445729



Photo 5. Reference vegetation to the east of well location. Vegetation near the road is lower quality and primarily Downy Brome though some desirable vegetation is present such as Smooth Brome.