

## Inspection Photos

Location Name: STATE-66N64W/36NESE

Location #: 327515



**Photo #1**

**State A36-9 (123-14790) Wellsite**

**Temporarily Abandoned | TA**

**Corrective Guidance: Weeds need cleared;  
Post OOSLAT tag at well.**



**Photo #2**

**Devries State A 36-21\*, A 36-23,  
Scholfield A36-20, State A36-9 Battery site**

**Inactive | Shut-down  
Equipment Documented; Fac ID: 302425**



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: STATE-66N64W/36NESE

Location #: 327515



### Photo #3

**Devries State A 36-21\*, A 36-23,  
Scholfield A36-20, State A36-9 Battery site**

**Inactive | Shut-down**

*Battery, wellsite(s) entrance*



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources