

# Final Reclamation Inspection

March 26, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 328997

Inspection Document #: 718800093

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: CLC RED W #15-15  
Location ID: 328997



**Photo 1.** Photo taken from the well location, facing North. Photo illustrates that the Operator has performed final reclamation activities with evidence of drill row seeding, however vegetation establishment does not meet Rule 1004 final reclamation standards.



**Photo 2.** Photo taken from the well location, facing East. See comments under Photo 1.



Inspection Photos  
Location Name: CLC RED W #15-15  
Location ID: 328997



**Photo 3.** Photo taken from the well location, facing south. See comments under Photo 1.



**Photo 4.** Photo taken from the well location, facing West. See comments under Photo 1.





Inspection Photos  
Location Name: CLC RED W #15-15  
Location ID: 328997



**Photo 5.** Photo taken from the well access road, facing west.  
See comments under Photo 1.



**Photo 6.** Photo taken of the associated tank battery location, facing north. Photo illustrates that the tank battery is still active for nearby well locations.



Inspection Photos  
Location Name: CLC RED W #15-15  
Location ID: 328997



**Photo 7.** Photo taken from the reference area, east of the location. Photo illustrates that reference areas are dominated by sand sagebrush.