

Final Reclamation Inspection

March 26, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 328998

Inspection Document #: 718800095

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CLC RED W #15-16
Location ID: 328998



Photo 1. Photo taken from the well location, facing North. Photo illustrates that the Operator has performed final reclamation activities with evidence of drill row seeding, however vegetation establishment does not meet Rule 1004 final reclamation standards.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.



Inspection Photos
Location Name: CLC RED W #15-16
Location ID: 328998



Photo 3. Photo taken from the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: CLC RED W #15-16
Location ID: 328998



Photo 5. Photo taken from the well access road, facing northeast. See comments under Photo 1.



Photo 6. Photo taken of the associated tank battery location, facing north. Photo illustrates that the tank battery is still active for nearby well locations.

Inspection Photos
Location Name: CLC RED W #15-16
Location ID: 328998



Photo 7. Photo taken from the reference area, west of the location, facing south.