

## Inspection Photos

Location Name: QB Energy RULISON FEDERAL 11-14 (RA11) Pad

Location #: 334688



Mar 31, 2025 at 12:31:55 PM

Photo # 8396 From Entrance to location



Mar 31, 2025 at 12:36:10 PM

Photo # 8397 Location

**Inspection Photos**  
**Location Name: QB Energy RULISON FEDERAL 11-14 (RA11) Pad**  
**Location #: 334688**



**Photo # 8398 Location**



**Photo # 8399 Location**



**Inspection Photos**  
**Location Name: QB Energy RULISON FEDERAL 11-14 (RA11) Pad**  
**Location #: 334688**



**Photo # 8400 Location**



**Photo # 8401 Location**



## Inspection Photos

Location Name: QB Energy RULISON FEDERAL 11-14 (RA11) Pad

Location #: 334688



**Photo # 8402 Hole in secondary containment liner/liner needs maintenance**



**Photo # 8403 Hole in secondary containment liner/liner needs maintenance**



## Inspection Photos

Location Name: QB Energy RULISON FEDERAL 11-14 (RA11) Pad

Location #: 334688



**Photo # 8404 Hole in secondary containment liner/liner needs maintenance**



**Photo # 8405 Hole in secondary containment liner/liner needs maintenance**



## Inspection Photos

Location Name: QB Energy RULISON FEDERAL 11-14 (RA11) Pad

Location #: 334688



**Photo # 8406 Hole in secondary containment liner/liner needs maintenance**



**Photo # 8407 Hole in secondary containment liner/liner needs maintenance**