

Inspection Photos

March 31st, 2025

Operator: Highpoint Operating - 10071

Location ID: 313612

Inspection Document #: 714002016

Montezuma County, CO

Township: SWSE 27 38N 16W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Koskie Brumley Draw 15H
Location ID: 313612

3/31/25
182° S



Photo 1. View of project area taken from the northern edge facing center. Note: location has pad, fill and cut slope have not been recontoured per 1004 reclamation standards.

Inspection Photos
Location Name: Koskie Brumley Draw 15H
Location ID: 313612



Photo 2. View of location fill slopes. Slopes have establishment of desirable vegetation including but not limited to Crested Wheatgrass, Sand Dropseed and Rabbitbrush.

Inspection Photos
Location Name: Koskie Brumley Draw 15H
Location ID: 313612

3/31/25
306° NW



Photo 3. View of flat portion of project area/pad taken from the southern edge facing center. Note: flat portion of project area has been revegetated with desirable vegetation including but not limited to Sand Dropseed, Crested Wheatgrass and Rabbitbrush.

Inspection Photos
Location Name: Koskie Brumley Draw 15H
Location ID: 313612



Photo 4. View of riser and location sign that remain at the access point of the location.