

Inspection Photos

03/25/2025

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 314334

Inspection Doc: 718100394

Rio Blanco County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 314334



Photo 1: Photos taken from the east end of the Location, facing southwest and northwest. Photos provide an overview of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 314334



Photo 2: Photo taken from the well. Pursuant to Form 6(s), well was cut/capped 10/24/2023. Pursuant to Rule 1004.a, surface equipment was required to be removed by 1/2024. Photo shows riser equipment remaining on the Location. Risers require removal.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 314334



Photo 3: Photo taken from the west end of the Location. Photo shows pipe riser remaining on the Location. BMPs to prevent wildlife access to the pipe are missing. Pipe requires removal.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 314334



Photo 4: Photo taken from the northeast end of the Location. Photo example showing anchor equipment remaining.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 314334



Photo 5: Unused cattle panels stored on the south end of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 314334



Photo 6: Photo shows the soil stockpile adjacent to the well. Photo also shows various trash/debris/rubbish mixed with the stockpile.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources