

Inspection Photos

03/25/2025

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 315260

Inspection Doc: 718100397

Rio Blanco County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 315260



Photo 1: Photos 1-2 taken from the former Location entrance, on the north end of the Location. Photos provide an overview of the Location from south, southwest, to west.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 315260



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 315260



Photo 3: Photos 3-4 taken from the central areas of the Location. Photos examples of areas where desirable, perennial plant establishment is not progressing towards ECMC 1004 uniform standards.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 315260



Photo 4: See comments under photo 3.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 315260



Photo 5: Photo taken from the southern areas of the Location, facing east. Photo example showing outer areas of the Location that are progressing towards 1004 standards.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 315260



Photo 6: Photo taken from the east end of the Location, facing north. Photo example showing outer areas of the Location that are progressing towards 1004 standards.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 315260



Photo 7: Photo example showing Noxious weed establishment (Common Mullein) observed throughout the Location. Additional weed management efforts required to prevent the further spread and establishment of Noxious weeds on this Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources