



Inspection Photos  
Spill/Release Name: Silt  
Produced Water Pipeline  
Spill/Release ID: 489603  
Inspection Date: March 20, 2025

Spill/release point. Fluids  
observed traveling to the  
south (right) and north  
(left).

Mar 20, 2025 1:51:12 PM  
+39.5042N -107.6588W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Spill/Release Name: Silt  
Produced Water Pipeline  
Spill/Release ID: 489603  
Inspection Date: March 20, 2025

Fluids to the south of the  
spill/release point pooling  
adjacent to Co Rd 331.

Mar 20, 2025 1:52:49 PM  
+39.5466N -107.6480W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Spill/Release Name: Silt  
Produced Water Pipeline  
Spill/Release ID: 489603  
Inspection Date: March 20, 2025

Fluids to the south of the  
spill/release point pooling  
adjacent to Co Rd 331.

Mar 20, 2025 1:52:54 PM  
+39.5466N -107.6480W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Spill/Release Name: Silt  
Produced Water Pipeline  
Spill/Release ID: 489603  
Inspection Date: March 20, 2025

Fluids to the south of the  
spill/release point pooling  
adjacent to Co Rd 331.

Mar 20, 2025 1:53:06 PM  
+39.5466N -107.6480W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Spill/Release Name: Silt  
Produced Water Pipeline  
Spill/Release ID: 489603  
Inspection Date: March 20, 2025

Spill/release point.  
Operator personnel were  
on location conducting  
mitigation and  
remediation activities.

Mar 20, 2025 1:54:41 PM  
+39.5042N -107.6587W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Spill/Release Name: Silt  
Produced Water Pipeline  
Spill/Release ID: 489603  
Inspection Date: March 20, 2025

Fluids traveling north of  
the spill/release point.

Mar 20, 2025 2:27:47 PM  
+39.5043N -107.6587W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Spill/Release Name: Silt  
Produced Water Pipeline  
Spill/Release ID: 489603  
Inspection Date: March 20, 2025

Fluids traveling north of the spill/release point. The fluids traveled through the subsurface from the south (left) side of the photo and daylighted on the north (right) side of the photo adjacent to the unnamed tributary of Dry Hallow Creek.

Mar 20, 2025 2:27:51 PM  
+39.5043N -107.6587W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Spill/Release Name: Silt  
Produced Water Pipeline  
Spill/Release ID: 489603  
Inspection Date: March 20, 2025

Fluids daylighting  
adjacent to the unnamed  
tributary of Dry Hallow  
Creek.

Mar 20, 2025 2:25:00 PM  
+39.5044N -107.6586W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



#### Inspection Photos

Spill/Release Name: Silt

Produced Water Pipeline

Spill/Release ID: 489603

Inspection Date: March 20, 2025

Fluids traveling north of the spill/release point and entering the unnamed tributary of Dry Hollow Creek. The fluids then traveled through the culvert under Co Rd 331.

Mar 20, 2025 2:26:27 PM  
+39.5044N -107.6586W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Spill/Release Name: Silt  
Produced Water Pipeline  
Spill/Release ID: 489603  
Inspection Date: March 20, 2025

Fluids traveling north of the spill/release point and entering the unnamed tributary of Dry Hollow Creek. The fluids then traveled through the culvert under Co Rd 331.

Mar 20, 2025 2:24:51 PM  
+39.5044N -107.6586W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Spill/Release Name: Silt  
Produced Water Pipeline  
Spill/Release ID: 489603  
Inspection Date: March 20, 2025

Fluids existing the culvert  
on the east side of Co Rd  
331.

Mar 20, 2025 2:21:43 PM  
+39.5043N -107.6583W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Spill/Release Name: Silt  
Produced Water Pipeline  
Spill/Release ID: 489603  
Inspection Date: March 20, 2025

Fluids traveling from the  
culvert towards the stock  
pond.

Mar 20, 2025 2:20:56 PM  
+39.5044N -107.6580W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Spill/Release Name: Silt  
Produced Water Pipeline  
Spill/Release ID: 489603  
Inspection Date: March 20, 2025

Confluence of the  
unnamed tributary of Dry  
Hallow Creek and the  
stock pond.

Mar 20, 2025 2:19:47 PM  
+39.5043N -107.6580W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Spill/Release Name: Silt  
Produced Water Pipeline  
Spill/Release ID: 489603  
Inspection Date: March 20, 2025

Stock pond looking east.

Mar 20, 2025 2:00:48 PM  
+39.5044N -107.6580W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Spill/Release Name: Silt  
Produced Water Pipeline  
Spill/Release ID: 489603  
Inspection Date: March 20, 2025

Stock pond looking southwest. Note the closed headgate on the east (left) side of the photo.

Mar 20, 2025 2:02:22 PM  
+39.5043N -107.6577W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Spill/Release Name: Silt  
Produced Water Pipeline  
Spill/Release ID: 489603  
Inspection Date: March 20, 2025

Stock pond looking northwest. Operator personnel were on location conducting sampling activities at the stock pond.

Mar 20, 2025 2:13:04 PM  
+39.5039N -107.6577W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Spill/Release Name: Silt  
Produced Water Pipeline  
Spill/Release ID: 489603  
Inspection Date: March 20, 2025

Dry Hallow Creek located  
east of the stock pond.

Mar 20, 2025 2:03:07 PM  
+39.5043N -107.6577W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Spill/Release Name: Silt  
Produced Water Pipeline  
Spill/Release ID: 489603  
Inspection Date: March 20, 2025

Dry Hallow Creek located  
east of the stock pond.

Mar 20, 2025 2:04:11 PM  
+39.5043N -107.6575W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Spill/Release Name: Silt  
Produced Water Pipeline  
Spill/Release ID: 489603  
Inspection Date: March 20, 2025

Dry Hallow Creek located  
east of the stock pond.

Mar 20, 2025 2:04:03 PM  
+39.5043N -107.6575W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources