

Inspection Photos
Location Name: Mantle #1, 4-2-28
Location ID: 332706



Photo 1: Location from entrance

Photo 2: Tank Battery Signs

Inspection Photos
Location Name: Mantle #1, 4-2-28
Location ID: 332706



Photo 3: Centralized tank battery

Photo 4: Wellhead Sign. Unused equipment

Inspection Photos
Location Name: Mantle #1, 4-2-28
Location ID: 332706



Photo 5: Unused equipment



Photo 6: Wellhead Sign. Unused equipment

Inspection Photos
Location Name: Mantle #1, 4-2-28
Location ID: 332706



Photo 7: Unused equipment

Photo 8: Equipment

Inspection Photos
Location Name: Mantle #1, 4-2-28
Location ID: 332706




Photo 9: Unused risers.

Photo 10: Unused risers

Inspection Photos
Location Name: Mantle #1, 4-2-28
Location ID: 332706




Photo 11: Unused riser