

Final Reclamation and Stormwater Inspection

March 25, 2025

Operator: WISE* WAYNE L - 97120

Location ID: 320012

Well Name: COLORADO STATE #32-12

Inspection Document #: 718600447

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: COLORADO STATE #32-12
Location ID: 320012



Photo 1. Looking east down access road from well API 001-07450. Vegetation coverage on road is lower than surrounding area and primarily undesirable weedy vegetation.



Photo 2. Looking east down access road from west side of fence junction. Undesirable weed Kochia is present on access road.



Inspection Photos
Location Name: COLORADO STATE #32-12
Location ID: 320012



Photo 3. Looking east down access road near fence line. Very little desirable vegetation establishment on access road, especially towards the west side. The crown of the road is visible in this picture, the road is elevated above the surrounding area and ditches are present on both sides.



Photo 4. Side profile of access road. Access road and ditches have not been recontoured flat.



Inspection Photos
Location Name: COLORADO STATE #32-12
Location ID: 320012



Photo 5. Looking across the turn around loop at the end of the road. Some desirable vegetation is present on the road but coverage is lower than surrounding area.



Photo 6. Picture taken at the northwest corner of location. Location is fenced. A large wire gate was down at time of inspection (red circle).

Inspection Photos
Location Name: COLORADO STATE #32-12
Location ID: 320012



Photo 7. Looking south across location. A large bare patch is present on the north side of location (red circle). List C noxious weed Downy Brome and undesirable weeds such as Kochia are present on location. Desirable perennial vegetation has begun to establish on portions of the location.



Photo 6. Picture taken on the west side of location, middle. Pipe remains on location.

Inspection Photos
Location Name: COLORADO STATE #32-12
Location ID: 320012



Photo 5. Picture taken on west side of location towards the south end. Debris on location (hose).



Photo 6. Overview of location looking north. There appears to be better desirable vegetation establishment on the south side of location.

Inspection Photos
Location Name: COLORADO STATE #32-12
Location ID: 320012



Photo 7. Reference vegetation to the north of location.