

# Final Reclamation and Stormwater Inspection

March 28, 2025

Operator: AXIS EXPLORATION LLC - 10646

Location ID: 460821

Well Name: BULLARD 6 (Tank Battery)

Inspection Document #: 718600457

Adams County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: BULLARD 6 (Tank Battery)  
Location ID: 460821



**Photo 1.** Looking west down access road. It appears that reclamation has been conducted with evidence of crimped straw.



**Photo 2.** Looking west from the center of tank battery. No oil and gas equipment remains. It appears that reclamation has been conducted with evidence of crimped straw.





Inspection Photos  
Location Name: BULLARD 6 (Tank Battery)  
Location ID: 460821



**Photo 3.** Looking south from center of tank battery. Crimped straw stops at fence line.



**Photo 4.** Looking east from center of tank battery. See photo 2 comments.





Inspection Photos  
Location Name: BULLARD 6 (Tank Battery)  
Location ID: 460821



**Photo 5.** Looking north from center of tank battery. See photo 2 comments.



**Photo 6.** Looking west down fence line. It appears that this fence was installed after the location and tank battery was constructed and it appears the tank battery extended south beyond the fence.





Inspection Photos  
Location Name: BULLARD 6 (Tank Battery)  
Location ID: 460821



**Photo 7.** Google earth aerial imagery taken 04/2024. It appears that the footprint of the well location and tank battery (red circle) extends over the fence line (approximate green line).