



Inspection Photos
Spill/Release Name: Silt
Produced Water Pipeline
Spill/Release ID: 489603
Inspection Date: March 21, 2025

Spill/release area.

Mar 21, 2025 11:23:31 AM
+39.5044N -107.6586W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Spill/Release Name: Silt
Produced Water Pipeline
Spill/Release ID: 489603
Inspection Date: March 21, 2025

Excavation containing the compromised flowline. Note the operator draining fluids from the flowline and removing with a vac truck.

Mar 21, 2025 11:53:43 AM
+39.5042N -107.6588W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Spill/Release Name: Silt
Produced Water Pipeline
Spill/Release ID: 489603
Inspection Date: March 21, 2025

Potentially impacted soils
stockpiled adjacent to the
flowline excavation.

Mar 21, 2025 11:54:53 AM
+39.5042N -107.6588W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Spill/Release Name: Silt
Produced Water Pipeline
Spill/Release ID: 489603
Inspection Date: March 21, 2025

Spill/release area looking
north.

Mar 21, 2025 11:53:40 AM
+39.5042N -107.6588W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Spill/Release Name: Silt
Produced Water Pipeline
Spill/Release ID: 489603
Inspection Date: March 21, 2025

Operator personnel running a temporary polyline from the stock pond to the existing flowline in the excavation for the removal of fluids from the stock pond.

Mar 21, 2025 12:06:25 PM
+39.5045N -107.6586W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Spill/Release Name: Silt
Produced Water Pipeline
Spill/Release ID: 489603
Inspection Date: March 21, 2025

Operator personnel running a temporary polyline from the stock pond to the existing flowline in the excavation for the removal of fluids from the stock pond.

Mar 21, 2025 12:07:05 PM
+39.5045N -107.6585W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Spill/Release Name: Silt
Produced Water Pipeline
Spill/Release ID: 489603
Inspection Date: March 21, 2025

Operator personnel
running a temporary
polyline from the stock
pond to the existing
flowline in the excavation
for the removal of fluids
from the stock pond.

Mar 21, 2025 12:05:16 PM
+39.5043N -107.6589W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources