



Inspection Photos
Spill/Release Name: Silt
Produced Water Pipeline
Spill/Release ID: 489603
Inspection Date: March 25, 2025

Spill/release area.

Mar 25, 2025 11:31:49 AM
+39.5044N -107.6586W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Spill/Release Name: Silt
Produced Water Pipeline
Spill/Release ID: 489603
Inspection Date: March 25, 2025

Excavation containing the compromised flowline (right side) and the temporary polyline (left side) used for the removal of fluids from the stock pond.

Mar 25, 2025 11:32:34 AM
+39.5043N -107.6587W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Spill/Release Name: Silt
Produced Water Pipeline
Spill/Release ID: 489603
Inspection Date: March 25, 2025

Excavation containing the compromised flowline (right side) and the temporary polyline (left side) used for the removal of fluids from the stock pond.

Mar 25, 2025 11:32:41 AM
+39.5043N -107.6587W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Spill/Release Name: Silt
Produced Water Pipeline
Spill/Release ID: 489603
Inspection Date: March 25, 2025

Stock pond looking south
east.

Mar 25, 2025 11:45:01 AM
+39 5044N -107 6580W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Spill/Release Name: Silt
Produced Water Pipeline
Spill/Release ID: 489603
Inspection Date: March 25, 2025

Stock pond and the
12-inch PVC line.

Mar 25, 2025 11:44:55 AM
+39.5044N -107.6580W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Spill/Release Name: Silt
Produced Water Pipeline
Spill/Release ID: 489603
Inspection Date: March 25, 2025

12-inch PVC line
diverting water to Dry
Hollow Creek.

Mar 25, 2025 11:45:37 AM
+39.5043N -107.6580W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Spill/Release Name: Silt
Produced Water Pipeline
Spill/Release ID: 489603
Inspection Date: March 25, 2025

12-inch PVC line
diverting water to Dry
Hollow Creek.

Mar 25, 2025 11:46:46 AM
+39.5044N -107.6579W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Spill/Release Name: Silt
Produced Water Pipeline
Spill/Release ID: 489603
Inspection Date: March 25, 2025

12-inch PVC line
diverting water to Dry
Hollow Creek.

Mar 25, 2025 11:47:34 AM
+39.5044N -107.6577W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Spill/Release Name: Silt
Produced Water Pipeline
Spill/Release ID: 489603
Inspection Date: March 25, 2025

Water diverted to Dry
Hollow Creek.

Mar 25, 2025 11:49:47 AM
+39.5044N -107.6578W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Spill/Release Name: Silt
Produced Water Pipeline
Spill/Release ID: 489603
Inspection Date: March 25, 2025

Dry Hollow Creek looking south.

Mar 25, 2025 11:48:28 AM
+39.5044N -107.6575W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Spill/Release Name: Silt
Produced Water Pipeline
Spill/Release ID: 489603
Inspection Date: March 25, 2025

Pooling fluids and stained
soils on the west side of
Co Rd 331.

Mar 25, 2025 11:33:10 AM
+39.5042N -107.6586W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Spill/Release Name: Silt
Produced Water Pipeline
Spill/Release ID: 489603
Inspection Date: March 25, 2025

Pooling fluids and stained
soils on the west side of
Co Rd 331.

Mar 25, 2025 11:35:02 AM
+39.5040N -107.6587W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Spill/Release Name: Silt
Produced Water Pipeline
Spill/Release ID: 489603
Inspection Date: March 25, 2025

Stained soils (green area)
adjacent to the unnamed
tributary to Dry Hollow
Creek located on the
west side of Co Rd 331.

Mar 25, 2025 11:54:32 AM
+39.5044N -107.6586W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Spill/Release Name: Silt
Produced Water Pipeline
Spill/Release ID: 489603
Inspection Date: March 25, 2025

Stained soils (green area)
adjacent to the unnamed
tributary to Dry Hollow
Creek located on the
west side of Co Rd 331.

Mar 25, 2025 11:31:07 AM
+39.5045N -107.6586W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources