

Inspection Photos

April 3rd, 2025

Operator: MorningStar Operating - 10755

Location ID: 320870

Inspection Document #: 714002040

Archuleta County, CO

Township: NENW 8 32N 5W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources



Photo 1. View of well pad taken from the access point facing center.



API #: 007-06183

Inspection Photos
Location Name: Candelaria 32-5 8-1
Location ID: 320870



Photo 2. Weedy debris @ secondary containment and rutting on active pad issues have been resolved.



Photo 3. Produced water not displaying current operator (“Southland Royalty” displayed).

Inspection Photos
Location Name: Candelaria 32-5 8-1
Location ID: 320870



Photo 4. Disconnected, unused exposed wires observed on the northern edge of the pad.