

Inspection Photos

April 3rd, 2025

Operator: Simcoe LLC - 10749

Location ID: 320859

Inspection Document #: 714002041

Archuleta County, CO

Township: SESE 17 32N 5W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Seibel B1
Location ID: 320859

Apr 3, 2025
+37.039607,-107.442463
130° SE



Apr 3, 2025
+36.984162,-106.940516
168° S

Photo 1. View of well pad taken from the access point facing center.



Apr 3, 2025
+37 020312,-107 408810
34° NE

Photo 2. Stained soils remain at wellhead.



Inspection Photos
Location Name: Seibel B1
Location ID: 320859

Apr 3, 2025
+37.020365,-107.408613
127° SE



Inspection Photos
Location Name: Seibel B1
Location ID: 320859



Apr 3, 2025
+37.020284, -107.408542
25° NE

Photo 4. Stormwater BMPs installed in the eastern portion of the location.