

Inspection Photos

April 3rd, 2025

Operator: Petrox Resources - 69805

Location ID: 378718

Inspection Document #: 714002042

Archuleta County, CO

Township: SESW 16 33N 5W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources



Photo 1. View of well pad taken from the access point facing center.



Photo 2. Gravel has been removed from produced water tank secondary containment.



Inspection Photos
Location Name: Wright 33-5 161
Location ID: 378718



Photo 3. Operator has performed recontouring and reseeding interim reclamation efforts on the location.

Inspection Photos
Location Name: Wright 33-5 161
Location ID: 378718



Photo 4. View of germination plot transects conducted in the fill and cut slopes of the location.