

# Inspection Photos

April 3rd, 2025

Operator: MorningStar Operating - 10755

Location ID: 320879

Inspection Document #: 714002044

Archuleta County, CO

Township: NESE 18 32N 5W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



**Photo 1.** View of well pad taken from the access point facing center. Note: well sign missing API #.









Inspection Photos  
Location Name: Hauschild 32-5 18-2  
Location ID: 320879





Inspection Photos  
Location Name: Hauschild 32-5 18-2  
Location ID: 320879



**Photo 4.** Gully erosion formed in the southern interim reclamation area.



Inspection Photos  
Location Name: Hauschild 32-5 18-2  
Location ID: 320879

