

Inspection Photos
Location Name: Shable 32-42
Location ID: 410065



Photo 1 – Lease Road – Erosion

Photo 2 – Lease Road – Erosion

Inspection Photos
Location Name: Shable 32-42
Location ID: 410065




Photo 3 – Sign at Entrance

Photo 4 – Pumping Unit

Inspection Photos
Location Name: Shable 32-42
Location ID: 410065



Photo 5 – Wellhead



Photo 6 – Wellhead Sign

Inspection Photos
Location Name: Shable 32-42
Location ID: 410065



Photo 5 – Erosion on Lease Road



Photo 6 – Pumping Unit