

Inspection Photos
Location Name: Heath PC GK 2-7
Location ID: 420545



Photo 1 – Sign at Entrance – Still shows previous Operators Contact Info

Photo 2 – Sign at Entrance – Still shows previous Operators Contact Info

Inspection Photos
Location Name: Heath PC GK 2-7
Location ID: 420545




Photo 3 – Pumping Unit



Photo 4 – Well Sign

Inspection Photos
Location Name: Heath PC GK 2-7
Location ID: 420545



Photo 5 – Pumping Unit




Photo 6 – Wellhead