

## Inspection/Audit Photos

Location: QB ENERGY COLOHAN-68S96W/4SENE (OH-4-8-96 PAD)

Location ID: 334150

Date: 04/3/2025



Photo # 6878 Entrance to location



Photo # 6924 Location

## Inspection/Audit Photos

Location: QB ENERGY COLOHAN-68S96W/4SENE (OH-4-8-96 PAD)

Location ID: 334150

Date: 04/3/2025



Photo # 6879 Location



Photo # 6900 Location

## Inspection/Audit Photos

Location: QB ENERGY COLOHAN-68S96W/4SENE (OH-4-8-96 PAD)

Location ID: 334150

Date: 04/3/2025



Photo # 6919 Location



Photo # 6950 Location

## Inspection/Audit Photos

Location: QB ENERGY COLOHAN-68S96W/4SENE (OH-4-8-96 PAD)

Location ID: 334150

Date: 04/3/2025



Photo # 6922 Location



Photo # 6951 SW corner of location

## Inspection/Audit Photos

Location: QB ENERGY COLOHAN-68S96W/4SENE (OH-4-8-96 PAD)

Location ID: 334150

Date: 04/3/2025



Photo # 6952 SE corner of location



Photo # 6953 NE corner of location

## Inspection/Audit Photos

Location: QB ENERGY COLOHAN-68S96W/4SENE (OH-4-8-96 PAD)

Location ID: 334150

Date: 04/3/2025



Photo # 6954 NW corner of location



Photo # 6914 PRV vent line does not comply with CECMC pressure safety device rules

## Inspection/Audit Photos

Location: QB ENERGY COLOHAN-68S96W/4SENE (OH-4-8-96 PAD)

Location ID: 334150

Date: 04/3/2025



Photo # 6918 Rupture disc vent line does not comply with CECMC pressure safety device rules



Photo # 6932 Methanol tank lacks required labeling/does not comply with CECMC rules

## Inspection/Audit Photos

Location: QB ENERGY COLOHAN-68S96W/4SENE (OH-4-8-96 PAD)

Location ID: 334150

Date: 04/3/2025



Photo # 6936 Methanol tank lacks required labeling/does not comply with CECMC rules

Photo # 6939 Debris on location



## Inspection/Audit Photos

Location: QB ENERGY COLOHAN-68S96W/4SENE (OH-4-8-96 PAD)

Location ID: 334150

Date: 04/3/2025



Photo # 6941 Debris on location



Photo # 6942 Debris on location

## Inspection/Audit Photos

Location: QB ENERGY COLOHAN-68S96W/4SENE (OH-4-8-96 PAD)

Location ID: 334150

Date: 04/3/2025




Photo # 6943 Debris on location



Photo # 6944 Debris on location

## Inspection/Audit Photos

Location: QB ENERGY COLOHAN-68S96W/4SENE (OH-4-8-96 PAD)

Location ID: 334150

Date: 04/3/2025



Photo # 6946 Debris on location



Photo # 6947 Debris on location

## Inspection/Audit Photos

Location: QB ENERGY COLOHAN-68S96W/4SENE (OH-4-8-96 PAD)

Location ID: 334150

Date: 04/3/2025



Photo # 6949 Debris on location



Photo # 6961 Unmarked deadman

## Inspection/Audit Photos

Location: QB ENERGY COLOHAN-68S96W/4SENE (OH-4-8-96 PAD)

Location ID: 334150

Date: 04/3/2025



Photo # 6962 Unmarked deadman



Photo # 6963 Unmarked deadman