

# Inspection Photos

Location Name: QB Energy CHRISTNER 8-5 (E8E) Pad

Location #: 334796



Photo # 9050 From Entrance to location




Photo # 9051 Location

# Inspection Photos

Location Name: QB Energy CHRISTNER 8-5 (E8E) Pad

Location #: 334796



Apr 3, 2025 at 3:09:11 PM  
CO



Apr 3, 2025 at 3:17:20 PM  
CO

Photo # 9052 Location

Photo # 9053 Location



**Inspection Photos**  
**Location Name: QB Energy CHRISTNER 8-5 (E8E) Pad**  
**Location #: 334796**



**Photo # 9054 Location**



**Photo # 9055 Location**



**Inspection Photos**  
**Location Name: QB Energy CHRISTNER 8-5 (E8E) Pad**  
**Location #: 334796**



**Photo # 9056 Unmarked deadman**

**Photo # 9057 Same unmarked deadman**



Inspection Photos  
Location Name: QB Energy CHRISTNER 8-5 (E8E) Pad  
Location #: 334796



Photo # 9058 Same unmarked deadman from a different angle



Photo # 9059 Weeds in secondary containment



**Inspection Photos**  
**Location Name: QB Energy CHRISTNER 8-5 (E8E) Pad**  
**Location #: 334796**



**Photo # 9060 Weeds in secondary containment**



**Photo # 9061 Weeds in secondary containment**