

# Inspection Photos

April 3rd, 2025

Operator: MorningStar Operating - 10755

Location ID: 333343

Inspection Document #: 714002058

Archuleta County, CO

Township: SESW 14 32N 6W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Peterson 32-6 14-2, 4  
Location ID: 333343



Apr 3, 2025  
310° NW



Photo 1. View of well pad taken from the access point facing center.



**Photo 2.** Wildlife netting has been installed at chemical tank secondary containment.

Inspection Photos  
Location Name: Peterson 32-6 14-2, 4  
Location ID: 333343



**Photo 3.** Stained soils removed from pump jack 14-2.

Apr 3, 2025  
213° SW



**Photo 4.** Weedy debris have been removed from produced water tank berms.