

Inspection Photos
Location Name: Kaufman PC GL20-68HZ
Location ID: 429749



Photo 1 – Wellhead



Photo 2 – Well Sign

Inspection Photos
Location Name: Kaufman PC GL20-68HZ
Location ID: 429749



Photo 3 – ECD and Separators



Photo 4 – Unmarked Riser

Inspection Photos
Location Name: Kaufman PC GL20-68HZ
Location ID: 429749



Photo 5 – Sign need reinstalled at Vault



Photo 6 – Unused parts at Compressor Building

Inspection Photos
Location Name: Kaufman PC GL20-68HZ
Location ID: 429749



Photo 7 – VRU



Photo 8 – Tank Battery – Sign missing

Inspection Photos
Location Name: Kaufman PC GL20-68HZ
Location ID: 429749



Photo 9 – Tank Battery – Sign missing



Photo 10 – Sign at Entrance