

Caerus Piceance LLC – QB Energy Corporation LLC
Freedom Unit-62S97W 28NWNW
Location ID: 335707



When replaced additional information is required.
Only 3 wells on pad.

Sign missing information and insufficient display

**Caerus Piceance LLC – QB Energy Corporation LLC
Freedom Unit-62S97W 28NWNW
Location ID: 335707**



Well pad from North corner



Well pad from South entrance

Caerus Piceance LLC – QB Energy Corporation LLC
Freedom Unit-62S97W 28NWNW
Location ID: 335707



Unused equipment



Unused equipment

Caerus Piceance LLC – QB Energy Corporation LLC
Freedom Unit-62S97W 28NWNW
Location ID: 335707



No tank battery sign



Replace when damaged

Caerus Piceance LLC – QB Energy Corporation LLC
Freedom Unit-62S97W 28NWNW
Location ID: 335707



Insufficient liner repair



Production pad from West corner