

Inspection Photos

Loc: 308057

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 4/7/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast along the access road. The erosion previously observed has been repaired with BMP's installed.



Inspection Photos



Photo 2. Facing west back down the road which has been repaired.



Inspection Photos



Photo 3. Facing northeast along the access road . This area has been repaired and reseeded. This area may need additional BMP's.



Inspection Photos



Photo 4. Facing north along the access road. This area has been built up with roadbase and crowing of the road.



Inspection Photos



Photo 5. Facing southeast toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:308057 | Date: 4/7/2025