

# Inspection Photos

API: 071-06237

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 4/7/2025

County: LAS ANIMAS



## Inspection Photos



**Photo 1.** Facing northwest toward the wellsite.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:071-06237 | Date: 4/7/2025

Inspection Photos



**Photo 2.** Facing west at the wellsite.



## Inspection Photos



**Photo 3.** Facing toward the northwest side of the location. This area has been regraded and reseeded.



## Inspection Photos



**Photo 4.** Facing southwest at the drainage crossing at the west side of the location. The culvert has been cleaned out and this area was reseeded..



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:071-06237 | Date: 4/7/2025