

Inspection Photos

API: 071-06230

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 4/7/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast along the access road. This area of the road was repaired and seeded. This long stretch of road may require additional BMP's to prevent erosion until vegetation establishes.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-06230 | Date: 4/7/2025

Inspection Photos



Photo 2. Facing back toward the repair along the road side. This area of the road may need additional BMP's such as rock check dams.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos



Photo 3. Facing north at the drainage crossing.



Inspection Photos



Photo 4. Facing southeast at the wellsite.

