

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 34-18 pad

Location ID: 324158



Photo # 9278 From entrance to location



Photo # 9279 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 34-18 pad

Location ID: 324158



Photo # 9280 Location



Photo # 9281 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 34-18 pad

Location ID: 324158




Photo # 9282 Location

Photo # 9283 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 34-18 pad

Location ID: 324158



Photo # 9284 Unmarked deadman



Photo # 9285 Same unmarked deadman

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 34-18 pad

Location ID: 324158



Photo # 9286 Same unmarked deadman from a different angle