

Inspection Photos

April 8th, 2025

Operator: Abundance Energy Services - 10840

Location ID: 325156

Inspection Document #: 714002063

La Plata County, CO

Township: SESE 9 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Ford Olson Unit 1
Location ID: 325156

Apr 8, 2025
196° S



Photo 1. View of well pad taken from the access point facing center.



Inspection Photos
Location Name: Ford Olson Unit 1
Location ID: 325156



Photo 2. Location cut slope/eastern interim reclamation area remains with mostly bare soils. Additional reclamation/seeding efforts are needed in this area. Wattle BMPs are functioning at this time.

Inspection Photos
Location Name: Ford Olson Unit 1
Location ID: 325156



Photo 3. Weedy debris and stormwater BMP issues from previous inspection have been addressed.