

Inspection Photos
Location Name: Twomile Creek 22-13H
Location ID: 422161



Photo 1 – Signs at Entrance are missing



Photo 2 – Unused Tanks

Inspection Photos
Location Name: Twomile Creek 22-13H
Location ID: 422161



Photo 3 – Tank Battery Site



Photo 4 – Tank Battery Site

Inspection Photos
Location Name: Twomile Creek 22-13H
Location ID: 422161



Photo 5 – Heater Treater



Photo 6 – Unused Parts and Equipment

Inspection Photos
Location Name: Twomile Creek 22-13H
Location ID: 422161



Photo 7 – Unused Parts and Equipment



Photo 8 – Unused Parts and Equipment

Inspection Photos
Location Name: Twomile Creek 22-13H
Location ID: 422161



Photo 9 – Unused Parts and Equipment



Photo 10 – Unused Parts and Equipment

Inspection Photos
Location Name: Twomile Creek 22-13H
Location ID: 422161




Photo 11 – Flare Inlet Line – valves appear to be open to Atmosphere



Photo 12 – Pumping Unit

Inspection Photos
Location Name: Twomile Creek 22-13H
Location ID: 422161



Photo 13 – Well Sign – Unused Well Parts



Photo 14 – Wellhead

Inspection Photos
Location Name: Twomile Creek 22-13H
Location ID: 422161




Photo 15 – Flowline Riser – Appears to be open to Atmosphere



Photo 16 – Unused Pipe at Pumping Unit