

Inspection Photos

04/07/2025

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 324113

Inspection Doc: 718100408

Garfield County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 324113



Photo 1: Photos taken from the southeast end of the Location, facing west and northwest. Photos provide an overview of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 324113



Photo 2: Photos taken from the eastern interim areas of the Location. Vegetation observed within photo appears to be predominantly cheatgrass. Desirable perennial vegetation is sparse within these areas.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 324113



Photo 3: Wildlife protection BMPs missing or insufficient at secondary containment.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 324113



Photo 4: Vehicle tracking controls do not appear to be sufficient to minimize erosion, degradation and vehicle tracking during wet condition; BMPs show signs of disrepair and tracking/rutting is becoming evident.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources