

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
404124598
Receive Date:
03/12/2025
Report taken by:
Grace Rollins

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECMC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27.

This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: NOBLE ENERGY INC	Operator No: 100322	Phone Numbers Phone: (970) 730-7281 Mobile: ()
Address: 1099 18TH STREET SUITE 1500		
City: DENVER	State: CO	Zip: 80202
Contact Person: Dan Peterson	Email: danpeterson@chevron.com	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 28380 Initial Form 27 Document #: 403340587

PURPOSE INFORMATION

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: _____

SITE INFORMATION

Yes Multiple Facilities

Facility Type: LOCATION	Facility ID: 332721	API #: _____	County Name: WELD
Facility Name: CORNELIUS-63N65W 11SWNW	Latitude: 40.244667	Longitude: -104.637442	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: SWNW	Sec: 11	Twp: 3N	Range: 65W Meridian: 6 Sensitive Area? Yes

Facility Type: SPILL OR RELEASE	Facility ID: 484505	API #: _____	County Name: WELD
Facility Name: CORNELIUS-63N65W 11SWNW	Latitude: 40.243611	Longitude: -104.637095	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: SWNW	Sec: 11	Twp: 3N	Range: 65W Meridian: 6 Sensitive Area? Yes

SITE CONDITIONS

General soil type - USCS Classifications SW _____

Most Sensitive Adjacent Land Use Rangeland _____

Is domestic water well within 1/4 mile? No _____

Is surface water within 1/4 mile? Yes _____

Is groundwater less than 20 feet below ground surface? No _____

Other Potential Receptors within 1/4 mile

Bald Eagle Roost Site
Emergent Wetlands 140ft SE, 115ft E, Riverine Wetlands (Gilmore Ditch) 0.10mi E, Freshwater Pond 0.08mi W, 0.12mi E
No other potential receptors are located within ¼ mile of the Site.
Above distances are approximations.

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- | | | |
|--|--|--|
| <input checked="" type="checkbox"/> E&P Waste | <input type="checkbox"/> Other E&P Waste | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids | _____ |
| <input checked="" type="checkbox"/> Oil | <input type="checkbox"/> Tank Bottoms | |
| <input checked="" type="checkbox"/> Condensate | <input type="checkbox"/> Pigging Waste | |
| <input type="checkbox"/> Drilling Fluids | <input type="checkbox"/> Rig Wash | |
| <input type="checkbox"/> Drill Cuttings | <input type="checkbox"/> Spent Filters | |
| | <input type="checkbox"/> Pit Bottoms | |
| | <input type="checkbox"/> Other (as described by EPA) | _____ |

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	GROUNDWATER	Further Investigation Required	Lab analysis
Yes	SOILS	45'x55'x8' deep	Lab analysis

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

A site investigation was conducted pursuant to ECMC Rule 911 at the CORNELIUS T3N-R65W-S11 L01 Facility and Tank Battery location.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Grab confirmation soil samples were collected from the produced water vessel(s) excavation, beneath the ground oil tank(s), and at the risers for the flowline(s) and dumpline(s) of any separator(s). Soil samples were analyzed by a certified laboratory for TPH (total volatile [C6-C10] and extractable [C10-C36] hydrocarbons), organic compounds in soil per ECMC Table 915-1, and EC, SAR, pH, and boron. All samples collected will be analyzed by a certified laboratory using approved ECMC laboratory analysis methods.

Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Groundwater was encountered during the site investigation and a grab groundwater was collected and analyzed for all organic compounds per ECMC Table 915-1.

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

Visual inspection of the tank battery area will occur during abandonment activities. Field personnel field screened all disturbed areas using visual and olfactory senses to determine if laboratory confirmation sampling is required.

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil	NA / ND
Number of soil samples collected <u>32</u>	-- Highest concentration of TPH (mg/kg) <u>290</u>
Number of soil samples exceeding 915-1 <u>19</u>	-- Highest concentration of SAR <u>9.86</u>

Was the areal and vertical extent of soil contamination delineated? Yes

BTEX > 915-1 No

Approximate areal extent (square feet) 2500

Vertical Extent > 915-1 (in feet) 8

Groundwater

Number of groundwater samples collected 2

-- Highest concentration of Benzene (µg/l) 9

Was extent of groundwater contaminated delineated? No

-- Highest concentration of Toluene (µg/l) 2.2

Depth to groundwater (below ground surface, in feet) 8

-- Highest concentration of Ethylbenzene (µg/l) 200

Number of groundwater monitoring wells installed 1

-- Highest concentration of Xylene (µg/l) 1400

Number of groundwater samples exceeding 915-1 2

NA Highest concentration of Methane (mg/l)

Surface Water

0 Number of surface water samples collected

Number of surface water samples exceeding 915-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Ten background soil samples were collected from an area not impacted by oil and gas development and at similar depths and lithologies as confirmation soil samples collected at the location and analyzed for Table 915 metals and soil suitability for reclamation constituents. Background soil sample analytical results were reported with elevated levels of arsenic, barium, chromium (VI), pH, boron, and SAR.

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

Is further site investigation required?

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? Yes

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Impacted soil will be removed from the release area by excavation. The impacted soil will be disposed of at an approved landfill as non-hazardous waste in accordance with Rules 905 and 906. Copies of the waste manifests will be available upon request.

REMEDICATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

The source will be excavated and confirmation soil samples will be collected and analyzed for the full Table 915-1 suite of analytes. Impacted groundwater was encountered during the site investigation impact delineation see the groundwater monitoring plan below. The proposed excavation is displayed on Figure 2 of Document number 403745826.

Following source removal of soil at the location, monitoring wells will be reinstalled and a no further action (NFA) determination will be requested once four consecutive quarters of groundwater sampling have been completed and reported at the location with concentrations of Table 915-1 constituents, detailed in the Groundwater Monitoring section, below regulatory limits. As needed, soil and/or groundwater remediation plans will be developed and submitted to ECMC in a supplemental Form 27.

Soil Remediation Summary

In Situ

Ex Situ

Bioremediation (or enhanced bioremediation)

Excavate and offsite disposal

Chemical oxidation

If Yes: Estimated Volume (Cubic Yards)

_____ Air sparge / Soil vapor extraction

_____ Natural Attenuation

_____ Other _____

_____ Name of Licensed Disposal Facility or ECMC Facility ID # _____

_____ Excavate and onsite remediation

_____ Land Treatment

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Other _____

Groundwater Remediation Summary

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Air sparge / Soil vapor extraction

_____ Natural Attenuation

_____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Noble Energy, Inc. proposes to install soil borings that will be improved with temporary PVC monitoring wells. One monitoring well was installed within the source area (if possible) and additional wells will be installed to monitor up-gradient, down-gradient, and cross-gradient groundwater conditions. Each soil boring location will have the soil type logged, will be field screened with a PID, and the interval with the highest PID measurement and/or the interval directly above groundwater will be collected and submitted for analysis of Table 915-1 constituents in soil. Quarterly groundwater monitoring will be completed until four consecutive quarters of groundwater sampling have been completed and reported at the location with concentrations of Table 915 constituents below regulatory limits. Groundwater monitoring wells will be sampled and submitted to a laboratory for analysis of Table 915-1 groundwater constituents: Benzene, Toluene, Ethylbenzene, Total Xylenes (BTEX), naphthalene, 1,2,4-Trimethylbenzene, 1,3,5-Trimethylbenzene, 1-Methylnaphthalene, 2- Methylnaphthalene Chloride ion, Sulfate ion and Total Dissolved Solids (TDS).

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

Quarterly Semi-Annually Annually Other

Request Alternative Reporting Schedule:

Semi-Annually Annually Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type: Groundwater Monitoring Land Treatment Progress Report O&M Report

Other Supplemental Form 27: Addressing Previous COAs and Timeline Update

Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Noble intends to directly address the costs of remediation at the locations as part of our asset retirement obligation process and operations. Noble has general liability insurance (policy MWZZ 316714) and financial assurance in compliance with ECMC rules. Records are available on the ECMC's website. The cost for remediation is an estimate only, costs may change upwards or downward based on site-specific information. Noble makes no representation or guarantees as to the accuracy of the estimate.

Operator anticipates the remaining cost for this project to be: \$ 50000

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards

E&P waste (solid) description

ECMC Disposal Facility ID #, if applicable:

Non-ECMC Disposal Facility:

Volume of E&P Waste (liquid) in barrels

E&P waste (liquid) description

ECMC Disposal Facility ID #, if applicable:

Non-ECMC Disposal Facility:

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

If YES:

Compliant with Rule 913.h.(1).

Compliant with Rule 913.h.(2).

Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? No

Does the previous reply indicate consideration of background concentrations?

Does Groundwater meet Table 915-1 standards? No

Is additional groundwater monitoring to be conducted? Yes

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation will be in accordance with ECMC 1000 Series Rules.

Is the described reclamation complete? Yes

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. 12/31/2025

Proposed date of completion of Reclamation. 12/31/2027

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 03/02/2023

Actual Spill or Release date, or date of discovery. 05/17/2023

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 04/20/2023

Proposed site investigation commencement. 05/02/2023

Proposed completion of site investigation. _____

REMEDIAL ACTION DATES

Proposed start date of Remediation. 12/31/2024

Proposed date of completion of Remediation. 12/31/2026

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

See Operator Comment

OPERATOR COMMENT

Addressing COAs provided 2/20/2025 on approved document number 404023107:

COA 1 Response:

The Operator has proposed a completion of remediation date of 12/31/2026 with consideration of the remedial actions needed to address soil and groundwater impacts. Additional groundwater monitoring wells will be installed 3/24/2025. Assuming four consecutive quarters of groundwater will be achieved within a years time on installation site closure would be requested 3/24/2026. However, excavation of impacted soil, scheduled for Q3 2025, will interrupt consecutive quarters of groundwater monitoring resetting the groundwater monitoring timeline. A minimum of one year of ECMC compliant groundwater monitoring will be needed following reinstallation of groundwater monitoring wells within 45 days of excavation completion.

COA 2 Response:

- The monitoring wells will be installed 3/24/2025.
- If impacts are observed during monitoring well installation a step out monitoring well(s) shall be installed to define the horizontal extent of impacts to soil and groundwater and the monitoring wells shall be installed within 45 days of observations.
- All monitoring wells will be constructed in accordance with the State Engineer's Water Well Construction and Permitting Rules
- Operator will provide boring logs in accordance with standard environmental practices. This includes at a minimum; lithology description, USCS classifications, PID readings, sample collection depths, depth to water, and well construction.
- Operator will submit a minimum of one soil sample for laboratory analysis of the previously approved list of contaminants of concern from each soil boring advanced during monitoring well installation. The sample(s) collected will be from the interval(s) displaying the highest degree of impact or in the absence of apparent impacts from the estimated historic high water table and/or above soil-groundwater interface.

COA 3 Response:

The Operator has updated the Groundwater Monitoring Plan to include analysis of 1-Methylnaphthalene and 2-Methylnaphthalene.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Ethan Black

Title: Consultant

Submit Date: 03/12/2025

Email: ethanb@fremontenv.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: Grace Rollins

Date: 04/10/2025

Remediation Project Number: 28380

COA Type

Description

	ECMC has processed this form as an update; no analytical was attached thus approval of this form does not imply any agreement with comments on completion of site investigation. All ongoing/unaddressed comments/COAs from previous Forms remain applicable.
	On the next quarterly Form 27 Supplemental, Operator shall update the Implementation Schedule based on soil and groundwater analytical data obtained from the site investigation.
2 COAs	

ATTACHMENT LIST

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num

Name

404124598	INVESTIGATION/REMEDATION WORKPLAN (SUPPLEMENTAL)
404161245	FORM 27-SUPPLEMENTAL-SUBMITTED

Total Attach: 2 Files

General Comments

User Group

Comment

Comment Date

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)