

# Inspection Photos

April 8th, 2025

Operator: Rim Operating - 74650

Location ID: 306973

Inspection Document #: 714002064

La Plata County, CO

Township: NWSE 20 33N 8W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Apr 8, 2025  
204° SW



**Photo 1.** View of well pad taken from the access point facing center.

Apr 8, 2025  
169° S



**Photo 2.** Rutting issues on active pad have been addressed/resolved.

