

## Inspection Photos

**Operator: AMERICAN HELIUM OPERATING LLC - 10841**

**Location Name: ANDY'S MESA FEDERAL #38**

**Location ID: 316838**

**API #: 05-113-06127**

**Inspection Date: 4/4/2025    Inspection Doc#: 693808300**



**Wellhead during Bradenhead test.  
Wellhead leaking at tbg/csg head.  
See Optical Gas Imaging section.**



**Separator and Meter housing**



## Inspection Photos

**Operator: AMERICAN HELIUM OPERATING LLC - 10841**

**Location Name: ANDY'S MESA FEDERAL #38**

**Location ID: 316838      API #: 05-113-06127**

**Inspection Date: 4/4/2025      Inspection Doc#: 693808300**



**Tank battery. Rusting tank.**



**Open top tank**

